

4. 权重表

4.1 理论知识权重表

项目	技能等级																														
	五级/初级工 (%)					四级/中级工 (%)					三级/高级工 (%)					二级/技师 (%)					一级/高级技师 (%)										
基本要求	职业道德	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5	5
	基础知识	15	15	20	15	25	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15	15
	绝缘装配	30	30	—	—	—	30	30	—	—	—	30	30	—	—	—	30	30	—	—	—	30	30	—	—	—	30	30	—	—	—
	引线装配	25	20	—	—	—	25	20	—	—	—	25	20	—	—	—	20	15	—	—	—	20	15	—	—	—	20	15	—	—	—
	总装配	25	30	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
	线圈处理	—	—	25	—	—	—	—	25	—	—	—	—	20	—	—	—	—	20	—	—	—	—	20	—	—	—	—	20	—	—
	器身处理	—	—	25	—	—	—	—	30	—	—	—	—	30	—	—	—	—	30	—	—	—	—	30	—	—	—	—	30	—	—
	消处理	—	—	—	25	—	—	—	—	25	—	—	—	—	30	—	—	—	—	10	—	—	—	—	15	—	—	—	—	15	—
	纵剪	—	—	—	—	25	—	—	—	—	25	—	—	—	—	25	—	—	—	—	15	—	—	—	—	15	—	—	—	—	—
	横剪	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—
叠装或卷制	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	
线圈空制准备	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	—	



## 4.2 技能要求权重表

项目	技能等级																													
	五级/初级工 (%)					四级/中级工 (%)					三级/高级工 (%)					二级/技师 (%)					一级/高级技师 (%)									
绝缘装配	40	45	—	—	—	40	45	—	—	—	—	—	—	—	—	20	25	—	—	—	—	—	—	—	—	—	—	—	—	—
引线装配	30	20	—	—	—	30	20	—	—	—	30	20	—	—	—	30	20	—	—	—	—	—	—	—	—	—	—	—	—	—
总装配	30	35	—	—	—	30	35	—	—	—	—	—	—	—	—	30	35	—	—	—	—	—	—	—	—	30	35	—	—	—
线圈处理	—	—	35	—	—	—	—	30	—	—	—	—	30	—	—	—	—	30	—	—	—	—	—	—	—	—	—	20	—	—
器身处理	—	—	35	—	—	—	—	40	—	—	—	—	35	—	—	—	—	30	—	—	—	—	—	—	—	—	—	30	—	—
油处理	—	—	30	—	—	—	—	30	—	—	—	—	30	—	—	—	—	10	—	—	—	—	—	—	—	—	—	20	—	—
纵剪	—	—	30	—	—	—	—	30	—	—	—	—	30	—	—	—	—	25	—	—	—	—	—	—	—	—	—	30	—	—
横剪	—	—	30	—	—	—	—	30	—	—	—	—	35	—	—	—	—	30	—	—	—	—	—	—	—	—	—	30	—	—
叠装或叠制	—	—	40	—	—	—	—	40	—	—	—	—	35	—	—	—	—	35	—	—	—	—	—	—	—	—	—	35	—	—
线圈绕制准备	—	—	25	—	—	—	—	25	—	—	—	—	20	—	—	—	—	20	—	—	—	—	—	—	—	—	—	20	—	—
线圈绕制	—	—	30	—	—	—	—	30	—	—	—	—	25	—	—	—	—	25	—	—	—	—	—	—	—	—	—	20	—	—
线圈压装	—	—	45	—	—	—	—	45	—	—	—	—	55	—	—	—	—	40	—	—	—	—	—	—	—	—	—	45	—	—
绝缘件开料	—	—	25	—	—	—	—	25	—	—	—	—	15	—	—	—	—	10	—	—	—	—	—	—	—	—	—	10	—	—
绝缘件压制	—	—	25	—	—	—	—	25	—	—	—	—	25	—	—	—	—	25	—	—	—	—	—	—	—	—	—	20	—	—
绝缘件机加工	—	—	25	—	—	—	—	25	—	—	—	—	30	—	—	—	—	25	—	—	—	—	—	—	—	—	—	20	—	—

